




m^2 = radiating area

Item	A	B	C	D	E	F	G	Brass Tube pcs	m^2	Flow l/min.	Weight kg
OR-60	450	305	46	89.1	121	3/4"	3/4"	22	0.3	60	8
OR-100	555	403	57	101.6	134	3/4"	3/4"	26	0.4	100	11
OR-150	575	385	76	139.8	175	1-1/4"	1"	42	0.63	150	18
OR-250	780	585	76	139.8	175	1-1/4"	1"	58	1.26	250	23
OR-350	1180	990	76	139.8	175	1-1/4"	1"	58	1.75	350	31
OR-600	1175	950	87	165.2	207	2"	1-1/4"	58	2.00	600	37
OR-800	1700	1490	87	165.2	207	2"	1-1/4"	58	2.90	800	50
OR-1000	2135	1910	87	165.2	207	2"	1-1/4"	58	3.70	1000	58
OR-1200	1625	1380	114	217	269	2-1/2"	2"	58	6.10	1200	103